Service info plics® software versions



VEGAFLEX 80 four-wire Modbus

Version, available since	Description	Device Rev.
1.0.1, 12/2022	 Error corrections: Instrument software, in general: Due to an initialization error of a 1-wire module, it could happen that the sensors did not start and output the error E036 	1
1.0.0, 01/2018	First version New functions and modifications relating to VEGAFLEX 80 four-wire Modbus (converter in second chamber):	1
	 Measurement function: No adaptations Instrument software, in general: Modbus-specific adaptations added Address setting on site via selection switch 	
	 PLICSCOM adjustment: Modification of the menu structure Modbus communication: Modbus communication integrated in sensor electronics Levelmaster communication completed in sensor software 	

Legend:

Name	Description
Version	Compatibility version.Function extension version.Error correction version
available since	Month/Year
Device Rev.	Version number of the instrument defined by HART. Consecutive integral number Will be increased if in the "Application Layer" modifications were carried out, e.g. new commands, modifications in the data structure in a command.